

Summary of Facility Information in the County of Madison

Owner Name and Address: Brian & Kim Beal PO Box 169 Alder MT 59710 Phone: (406) 842-5679

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|--------------------|-------------------------|---------------|-------|----------------|
| 2804167 | Beals Alder Market | 1st & Main St | Alder | 59710 | (406) 842-5679 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|-------------------|------------------------------------------------|-------------------------------------|-------------|--------------------------------------------------------------------------------|-------------------------|
| 2 / S4 Currently In Use | 386 | 7/1/1988 18 / Ye | Gasoline 2,900 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / S3 Currently In Use | 385 | 7/1/1988 18 / Ye | Gasoline 3,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Madison

Owner Name and Address: David Kelly Galloup 50 US Highway 287 S Cameron MT 59720 Phone: (406) 682-4804

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------|-------------------------|---------------|-------|----------------|
| 2805820 | Slide Inn Inc | 50 US Highway 287 S | Cameron | 59720 | (406) 682-4804 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|----------------------------------|-----------|----------------------|---------------------|------------------------------------------------|---------------------------------------|--------------|-------------------------------------------------------------|-------------------------|
| 5 / 05 Temporarily Out of Use | 4015 | 5/1/1999 07 / No | Gasoline 4,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A●●DEFGHIJKL</div> <div>BDEFGHI●K L</div> </div> | Yes Yes Yes Yes |
| 6 / 06 Temporarily Out of Use | 4016 | 5/1/1999 07 / No | Gasoline 4,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A●●DEFGHIJKL</div> <div>BDEFGHI●K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Madison

Owner Name and Address: Ennis School Dist 52 PO Box 517 Ennis MT 59729 Phone: (406) 682-4258

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|----------------------|-------------------------|---------------|-------|----------------|
| 2803517 | Ennis School Dist 52 | 323 Charles St | Ennis | 59729 | (406) 682-4258 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|-----------------------|------------------------------------------------|-------------------------------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| 6 / S6 Currently In Use | 1571 | 10/1/1998 07 / No | Heating Oil 10,000 | STI-P3 Double-Walled | Flexible Plastic Double-Walled | Gravity Feed | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 7 / S7 Currently In Use | 1572 | 10/1/1998 07 / No | Heating Oil 2,000 | Polyethylene Tank Jacket Double-Walled | Flexible Plastic Double-Walled | Gravity Feed | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 8 / S8 Currently In Use | 1573 | 10/1/1998 07 / No | Heating Oil 2,000 | Polyethylene Tank Jacket Double-Walled | Flexible Plastic Double-Walled | Gravity Feed | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Madison

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------|-------------------------|---------------|-------|----------------|
| 2808698 | Town Pump Inc Ennis | 116 W Main St | Ennis | 59729 | (406) 682-7439 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|-----------------------|--------------------|------------------------------------------------|---------------------------------------|-------------|--------------------------------------------------------------------------------|-------------------------|
| 1 / 01 Currently in Use | 2529 | 4/14/1980 26 / No | Diesel 12,000 | STI-P3 None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / 04 Currently in Use | 2530 | 4/1/1992 14 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 5 / 05 Currently in Use | 2531 | 4/1/1992 14 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 6 / 06 Currently in Use | 2532 | 4/1/1992 14 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 7 / 07 Currently in Use | 4734 | 10/16/2002 03 / No | Diesel 6,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 8 / 08 Currently in Use | 4735 | 10/16/2002 03 / No | Diesel 5,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Madison

Owner Name and Address: Rocky Mountain Supply Inc PO Box 129 Belgrade MT 59714 Phone: (406) 388-4008

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------------------|-------------------------|---------------|-------|----------------|
| 5613826 | Rocky Mountain Supply Inc Ennis | 4997 US Highway 287 N | Ennis | 59729 | (406) 682-4315 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|--------------------|------------------------------------------------|-------------------------------------|-------------|--------------------------------------------------------------------------------|-------------------------|
| 1 / 01 Currently In Use | 1768 | 7/1/1997 09 / No | Diesel 8,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C ● E F G H I J K L</div> <div>B D E F ● H I ● K L</div> </div> | Yes Yes Yes Yes |
| 2 / 02 Currently In Use | 1769 | 7/1/1997 09 / No | Diesel 5,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C ● E F G H I J K L</div> <div>B D E F ● H I ● K L</div> </div> | Yes Yes Yes Yes |
| 3 / 03 Currently In Use | 1770 | 7/1/1997 09 / No | Diesel 8,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C ● E F G H I J K L</div> <div>B D E F ● H I ● K L</div> </div> | Yes Yes Yes Yes |
| 4 / 04 Currently In Use | 1771 | 7/1/1997 09 / No | Diesel 5,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C ● E F G H I J K L</div> <div>B D E F ● H I ● K L</div> </div> | Yes Yes Yes Yes |
| 5 / 05 Currently In Use | 1772 | 7/1/1997 09 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C ● E F G H I J K L</div> <div>B D E F ● H I ● K L</div> </div> | Yes Yes Yes Yes |
| 6 / 06 Currently In Use | 1773 | 7/1/1997 09 / No | Gasoline 8,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C ● E F G H I J K L</div> <div>B D E F ● H I ● K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Madison

Owner Name and Address: Sam and Sherry Scott 3799 S Meadow Creek Road Mc Allister MT 59740 Phone: (406) 682-4445

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|----------------------------|-------------------------|---------------|-------|----------------|
| 2806262 | Crossroads Market & Cabins | 5564 US Highway 287 | Mc Allister | 59740 | (406) 682-7652 |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Piping Release Detection | FR Met |
|------------------------|-----------|-------------------|------------------|---------------------------------------------|----------------------------------|--------------|--------------------------------------|--------------------------------|-------------|
| 3 / 03 | 3313 | 10/21/1998 | Gasoline | Polyethylene Tank Jacket | Flexible Plastic | Safe Suction | (A)(B)(C)(D)(E)(F)(●)(H)(I)(J)(K)(L) | (B)(D)(E)(F)(G)(H)(I)(●)(K)(L) | Yes |
| Temporarily Out of Use | | 07 / No | 1,000 | Double-Walled | None | | | | Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Madison

Owner Name and Address: A M Welles Inc PO Box 2808 Norris MT 59745 Phone: (406) 685-3372

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-----------------------------|-------------------------|---------------|-------|----------------|
| 5614138 | McLeod Mercantile SW Corner | 6533 US Highway 287 S | Norris | 59745 | (406) 685-3361 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|-------------------|------------------------------------------------|---------------------------------------|-------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| 1 / 10 Currently in Use | 2716 | 7/1/1991 15 / No | Gasoline 1,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 11 Currently in Use | 2717 | 7/1/1991 15 / No | Diesel 1,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 10 / 06 Currently in Use | 2712 | 7/1/1991 15 / No | Gasoline 2,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 11 / 08 Currently in Use | 2714 | 7/1/1991 15 / No | Gasoline 2,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 12 / 07 Currently in Use | 2713 | 7/1/1991 15 / No | Gasoline 2,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 13 / 09 Currently in Use | 2715 | 7/1/1991 15 / No | Gasoline 6,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 14 / 14 Currently In Use | 4892 | 7/2/2004 01 / No | Diesel 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Madison

Owner Name and Address: A M Welles Inc PO Box 2808 Norris MT 59745 Phone: (406) 685-3372

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------------|-------------------------|---------------|-------|----------------|
| 2802043 | McLeod Mercantile 2802043 | 202 S Main St | Sheridan | 59749 | (406) 842-5477 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|-------------------|------------------------------------------------|---------------------------------------|--------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| 1 / 10 Currently in Use | 2951 | 11/1/1995 10 / No | Diesel 4,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |
| 2 / 11 Currently in Use | 2952 | 11/1/1995 10 / No | Gasoline 4,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |
| 3 / 12 Currently in Use | 2953 | 11/1/1995 10 / No | Gasoline 4,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |
| 8 / 09 Currently in Use | 2950 | 11/1/1995 10 / No | Gasoline 4,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Madison

Owner Name and Address: A M Welles Inc PO Box 2808 Norris MT 59745 Phone: (406) 685-3372

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------|-------------------------|---------------|-------|----------------|
| 6015002 | A M Welles | Left at 95 Tuke Lane | Sheridan | 59749 | |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | FR Met | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------------|-----------|----------------------|----------------------------------|------------------------------------------------|-------------------------------------|----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---|---|----------------------------------|---|---|---|---|---|---|---|---|---|--|---|--|---|---|----------------------------------|---|---|---|---|---|--------------------|
| Status | | | | | | | Piping Release Detection | Spill/Overl/C | | | | | | | | | | | | | | | | | | | | | | | | |
| 1 / 01 Currently in Use | 5044 | 9/15/2005 00 / No | Diesel 15,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 2 / 02 Currently in Use | 5007 | 9/15/2005 00 / No | Diesel 15,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 3 / 03 Currently in Use | 5008 | 9/15/2005 00 / No | Diesel 8,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 4 / 04 Currently in Use | 5009 | 9/15/2005 00 / No | Diesel 7,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 5 / 05 Currently in Use | 5010 | 9/15/2005 00 / No | Gasoline 15,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 6 / 06 Currently in Use | 5011 | 9/15/2005 00 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Madison

Owner Name and Address: Bo Mailey PO Box 434 Twin Bridges MT 59754 Phone: (406) 684-5611

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|------------------------------|-------------------------|---------------|-------|----------------|
| 2807478 | Bos Chevron and Tire Service | 100 S Main St | Twin Bridges | 59754 | (406) 684-5611 |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction | Piping Material | | Tank Release Detection | FR Met | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------------|-----------|---------------------|-------------------|-------------------------------------------|---------------------------------------|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---|---|---|---|---|---|---|---|---|---|---|---|--|--|---|---|---|---|---|---|---|---|---|--------------------|
| Status | | | | Secondary Option | Secondary Option | Piping Type | Piping Release Detection | Spill/Overl/C | | | | | | | | | | | | | | | | | | | | | | | | |
| 5 / 05 Currently In Use | 3913 | 1/1/1999 07 / No | Gasoline 1,000 | Polyethylene Tank Jacket Double-Walled | Fiberglass Reinforced Plastic None | Safe Suction | <table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>●</td><td>K</td><td>L</td></tr></table> | A | B | C | D | E | F | ● | H | I | J | K | L | B | | | D | E | F | G | H | I | ● | K | L | Yes Yes Yes Yes |
| A | B | C | D | E | F | ● | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | | D | E | F | G | H | I | ● | K | L | | | | | | | | | | | | | | | | | | | | | |
| 6 / 06 Currently In Use | 3914 | 1/1/1999 07 / No | Gasoline 1,000 | Polyethylene Tank Jacket Double-Walled | Fiberglass Reinforced Plastic None | Safe Suction | <table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>●</td><td>K</td><td>L</td></tr></table> | A | B | C | D | E | F | ● | H | I | J | K | L | B | | | D | E | F | G | H | I | ● | K | L | Yes Yes Yes Yes |
| A | B | C | D | E | F | ● | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | | D | E | F | G | H | I | ● | K | L | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Madison

Owner Name and Address: Richard T & Catherine L Pratt PO Box 261 Twin Bridges MT 59754 Phone: (406) 684-5733

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|--------------------|-------------------------|---------------|-------|----------------|
| 2810708 | Three Rivers Cenex | 325 S Main St | Twin Bridges | 59754 | (406) 684-5733 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|-------------------|------------------------------------------------|---------------------------------------|--------------|------------------------------------------------------------------------------|-------------------------|
| 4 / 04 Currently in Use | 1816 | 10/1/1992 13 / No | Gasoline 3,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I K L</div> </div> | Yes Yes Yes Yes |
| 5 / 05 Currently in Use | 1817 | 10/1/1992 13 / No | Gasoline 5,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Madison

Owner Name and Address: Madison County Commissioners PO Box 278 Virginia City MT 59755 Phone: (406) 843-4277

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|--------------------------------------|-------------------------|---------------|-------|----------------|
| 2800401 | Courthouse & Thompson Hickman Librar | 110 E Wallace St | Virginia City | 59755 | (406) 843-4277 |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Piping Release Detection | FR Met |
|----------------------------|-----------|---------------------|------------------|---------------------------------------------|-----------------------------------|--------------|----------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|--------------------|
| 5 / 05 Currently In Use | 1570 | 8/1/1998 07 / No | Diesel 2,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Gravity Feed | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |